



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20241205142409
Test Time: 2024-12-05 14:24:09
Technician: Travino

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0184247
Odometer Reading: 18630
License Plate: FXG759L

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.00
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(2)

System	Status/DTC
Air bag	0
BCM	6

DTC (6)

BCM (6 DTCs)

DTC	Description	Status
000100	Front windshield wiper park circuit	
004002	Siren circuit	
P0000	Decoder -> ring connection	
P0000	Impact detected signal	
000100	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	

Technician Notes

2016649680

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.