Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261027114112
Test Time: 2026-10-27 11:41:12
Technician: Werner

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0187233

Odometer Reading: 151588
License Plate: JV72CMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (2)

System	Status/DTC
Air bag	8
BCM	3

DTC (11)

Air bag (8 DTCs)

DTC	Description	Status
903441	Airbag malfunction indicator lamp (MIL) circuit	Past
B1041	Passenger airbag status lamp circuit	Past
903441	Please refer to vehicle service manual.	
B107C	Passenger airbag lock status change	Past
B1005	Passenger front airbag circuit	Past
B107F	Replace ECU after impact	Current
B1042	ECU supply voltage	Past
B1007	Drivers front airbag circuit	Current

BCM (3 DTCs)

DTC	Description	Status
002002	Please refer to vehicle service manual.	
010600	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	

Technician Notes

2017317864

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.