Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261007100053
Test Time: 2026-10-07 10:00:53
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0194687

Odometer Reading: 143661
License Plate: MC78PMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (2)

System	Status/DTC
Air bag	3
BCM	4

DTC (7)

Air bag (3 DTCs)

DTC	Description	Status
B1040	Airbag malfunction indicator lamp (MIL) circuit	Past
B1041	Passenger airbag status lamp circuit	Past
B1042	ECU supply voltage	Past

BCM (4 DTCs)

DTC	Description	Status
000100	Please refer to vehicle service manual.	
042002	Please refer to vehicle service manual.	
010B00	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	

Technician Notes

2017308480

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.