



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250506141259
Test Time: 2025-05-06 14:12:59
Technician: Werner

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0199549

Odometer Reading: 116979
License Plate: KJ62YFGP

Customer Information

Name: Dekra MFC AUCTION HOUSE



Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.10

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(2)

System	Status/DTC
Air bag	 0
BCM	 5

DTC (5)

BCM (5 DTCs)

DTC	Description	Status
000100	Front windshield wiper park circuit	
402002	Please refer to vehicle service manual.	
030A00	Please refer to vehicle service manual.	
004002	Siren circuit	
004002	Please refer to vehicle service manual.	

Technician Notes

2016866193

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

