Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261023123112
Test Time: 2026-10-23 12:31:12
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0210214

Odometer Reading: 149392
License Plate: KT64LTGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (2)

System	Status/DTC
Air bag	3
BCM	3

DTC (6)

Air bag (3 DTCs)

DTC	Description	Status
B1042	ECU supply voltage	Past
B107C	Passenger airbag lock status change	Past
B1005	Passenger front airbag circuit	Past

BCM (3 DTCs)

DTC	Description	Status
000100	Please refer to vehicle service manual.	
442002	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	

Technician Notes

2017316486

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.