



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250813114011
Test Time: 2025-08-13 11:40:11
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN365U0151512

Odometer Reading: 245291
License Plate: HP64FXGP

Customer Information

Name: Dekra MFC AUCTION HOUSE






Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.30

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine	 7
ABS	 1
Air bag	 1
Electric Power Steering (EPS)/DAST 3	 1
BCM	 4

DTC (14)

Engine (7 DTCs)

DTC	Description	Status
P0110	Inlet air temperature sensor circuit	Current
P0380	Preheating unit diagnosis connection	Current
P3264	Water in diesel warning lamp circuit	Past
P0685	Main relay control circuit	Past
P2269	Water in diesel fuel	Current
P0560	ECU supply voltage	Past
P0513	Engine immobilizer	Past

ABS (1 DTC)

DTC	Description	Status
C10CC	ECU power supply	Past

Air bag (1 DTC)

DTC	Description	Status
B1042	ECU supply voltage	Past

Electric Power Steering (EPS)/DAST 3 (1 DTC)



DTC	Description	Status
560128	Please refer to vehicle service manual.	

BCM (4 DTCs)

DTC	Description	Status
000100	Please refer to vehicle service manual.	
042000	Please refer to vehicle service manual.	
000200	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	

Technician Notes
2016978055

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.