Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261116125807
Test Time: 2026-11-16 12:58:07
Technician: Sbu

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/Ranger / Mazda B-Series / Troller/--
VIN: AFAPXXMJ2PHU45586

Odometer Reading: 246432
License Plate: FT83LGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
PCM(Powertrain control module)	0
ABS(Anti-lock brake system)	0
RCM(Restraint control module)	0
IPC(Instrument panel control module)	0
ACM(Audio control module)	0
BdyCM(Body control module) ADAS	0
FCIM(Front controls interface module)	0
GWM(Gateway module A)	0
PSCM(Power steering control module)	0
RTM(Radio transceiver module)	0
SCCM(Steering column control module)	0
TRM(Trailer module)	0

DTC (0)

Technician Notes

2017326184

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.