



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250618124200
Test Time: 2025-06-18 12:42:00
Technician: Andrick

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/Ranger / Mazda B-Series / Troller/--
VIN: AFAPXXMJ2PLB74466

Odometer Reading: 171432
License Plate: JL41HZGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V8.90

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(15)

System		Status/DTC
PCM(Powertrain control module)		 4
TCM(Transmission control module)		 0
ABS(Anti-lock brake system)		 0
RCM(Restraint control module)		 0
IPC(Instrument panel control module)		 1
APIM(Accessory protocol interface module)		 0
BdyCM(Body control module)		 1
FCIM(Front controls interface module)		 0
GWM(Gateway module A)		 0
IPMA(Image processing module A)		 0
PAM(Parking aid module)		 0
PSCM(Power steering control module)		 0
RTM(Radio transceiver module)		 0
SCCM(Steering column control module)		 0
TRM(Trailer module)		 0

DTC (6)

PCM(Powertrain control module) (4 DTCs)

DTC	Description	Status
P02FA:02-68	Diesel Intake Air Flow Position Sensor Minimum/Maximum Stop Performance	CMDTCs



P02FA:68-68	Diesel Intake Air Flow Position Sensor Minimum/Maximum Stop Performance	CMDTCs
P2267:00-2F	Water in Fuel Sensor A Circuit High	CMDTCs
P261B:00-2F	Coolant Pump B Control Circuit Performance/Stuck Off	CMDTCs

IPC(Instrument panel control module) (1 DTC)

DTC	Description	Status
U0100:00-08	Lost Communication With ECM(Electronic Control Module)/PCM(Powertrain Control Module) A	CMDTCs

BdyCM(Body control module) (1 DTC)

DTC	Description	Status
B1313:15-0A	Interior Lighting Output	CMDTCs

Technician Notes
2016915590

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.