Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261029122830
Test Time: 2026-10-29 12:28:30
Technician: Werner

2015 MY(Model Year) Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

2015 MY(Model Year)/Ford/Ranger / Mazda B-Series / Troller/--
VIN: AFAPXXMJ2PLT55247

Odometer Reading: 202915
License Plate: LGG614NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (14)

System	Status/DTC
PCM(Powertrain control module)	1
TCM(Transmission control module)	0
ABS(Anti-lock brake system)	1
RCM(Restraint control module)	0
IPC(Instrument panel control module)	0
ACM(Audio control module)	0
BdyCM(Body control module) ADAS	5
FCIM(Front controls interface module)	0
GWM(Gateway module A)	0
PAM(Parking aid module) ADAS	3
PSCM(Power steering control module)	1
RTM(Radio transceiver module)	0
SCCM(Steering column control module)	1
TRM(Trailer module)	0

DTC (12)

PCM(Powertrain control module) (1 DTC)

DTC	Description	Status
P0532:00-2F	Air conditioning Refrigerant Pressure Sensor A Circuit Low	CMDTCs

ABS(Anti-lock brake system) (1 DTC)

DTC	Description	Status
U3003:16-08	Battery voltage	CMDTCs

BdyCM(Body control module) (5 DTCs)

DTC	Description	Status
B1313:15-08	Interior Lighting Output	CMDTCs
U3006:16-08	Control Module Input Power A Circuit / Open	CMDTCs
U3007:16-08	Control Module Input Power B Circuit / Open	CMDTCs
U3013:16-08	Control Module Input Power C Circuit / Open	CMDTCs
U3014:16-08	Control Module Input Power D Circuit / Open	CMDTCs

PAM(Parking aid module) (3 DTCs)

DTC	Description	Status
B1B44:96-2B	Right Rear Outer Sensor	CMDTCs
B1B48:14-2B	Left Rear Outer Sensor	CMDTCs
B1B50:96-2B	Left Rear Inner Sensor	CMDTCs

PSCM(Power steering control module) (1 DTC)

DTC	Description	Status
U0140:00-08	Lost Communication With Body Control Module	CMDTCs

SCCM(Steering column control module) (1 DTC)

DTC	Description	Status
B11D9:16-08	Vehicle Battery	CMDTCs

Technician Notes

2017318911

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.