



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231222093109
Test Time: 2023-12-22 09:31:09
Technician: Sbu

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/Ranger/--

VIN: AFAPXXMJ2PPK15055

Odometer Reading: 17800

License Plate: N o n e r e g n u m b e r

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V8.20

Repair Order Number: --

System Scanned(23)

System		Status/DTC
PCM(Powertrain control module)		✓ 0
TCM(Transmission control module)		✓ 0
ABS (Anti-lock Brake System)		✗ 2
RCM (Restraint Control Module)		✓ 0
IPC (Instrument Panel Control Module)		✓ 0
ACM (Audio Control Module)		✓ 0
APIM (Accessory Protocol Interface Module)		✓ 0
BCM-C (Body Control Module C)		✓ 0
BdyCM(Body control module)	ADAS	✓ 0
DDM (Driver Door Module)		✓ 0
FCIM-B (Front Controls Interface Module B)		✓ 0
GWM (Gateway Module A)		✓ 0
HVAC (Heating Ventilation Air Conditioning)		✓ 0
IPM-A (Image Processing Module A)	ADAS	✓ 0
PDM (Passenger Door Module)		✓ 0
PSCM (Power Steering Control Module)		✓ 0
RTM (Radio Transceiver Module)		✓ 0
SCCM (Steering Column Control Module)		✓ 0



SOD-L (Side Obstacle Detection Control Module - Left)	ADAS	✓ 0
SOD-R (Side Obstacle Detection Control Module - Right)	ADAS	✓ 0
TCU (Telematic Control Unit)		✓ 0
TRM (Trailer Module)		✓ 0
WACM (Wireless Accessory Charging Module)		✓ 0

 DTC (2)

ABS (Anti-lock Brake System) (2 DTCs)

DTC	Description	Status
U0146:00-68	Lost Communication With Serial Data Gateway A	CMDTCs
U0256:00-28 A	Lost Communication With Front Controls Interface Module A	CMDTCs

Technician Notes

2016209963

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.