

Mazda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mazda/BT-50/--

VIN: AFBTXXMJ2TBL13733

Odometer Reading: 397230

License Plate: DK99PMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V9.31

Serial Number: VB8GJCC01509

Repair Order Number: --



System Scanned (2)

System	Status/DTC
ABS(Anti-lock brake system/traction control module)	1
RCM(Restraint control module)	3



DTC (4)

ABS(Anti-lock brake system/traction control module) (1 DTC)

DTC	Description	Status
C1096	Pump Motor Open Circuit	CMDTCs

RCM(Restraint control module) (3 DTCs)

DTC	Description	Status
B1318	Battery Voltage Low	CMDTCs
B1994	Side Air Bag Circuit Open, Front Driver Side	CMDTCs
B1998	Side Air Bag Circuit Open, Front Passenger Side	CMDTCs

Technician Notes

2017302465

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.