Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTAA3DC701714857

Odometer Reading: 53245km
License Plate: HMF849L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (19)

System		Status/DTC
Engine and transmission		0
Brake		0
SRS airbag		0
Combination meter		1
Pre-Collision system	ADAS	0
Front radar sensor	ADAS	0
Navigation system		0
Starting control		0
Power source control		0
Entry&Start		0
Headlamp auto leveling	ADAS	0
Clearance sonar	ADAS	0
Central gateway		0
Radar cruise 1	ADAS	0
Radar cruise 2	ADAS	0
Lane control	ADAS	0
Front recognition camera	ADAS	0
PPS		0
4WD		0

DTC (1)

Combination meter (1 DTC)

DTC	Description	Status
B150A	Lost communication with HMI-LAN	History

Technician Notes

2017316644

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.