Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261016093436
Test Time: 2026-10-16 09:34:36
Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTCW8CB701966057

Odometer Reading: 133268km
License Plate: HMT959L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
Engine and ECT	0
ABS/VSC/TRC	0
SRS airbag	0
Combination meter	0
Radar cruise 1 ADAS	0

DTC (0)

Technician Notes

2017313061

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.