



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250730153615  
Test Time: 2025-07-30 15:36:15  
Technician: Clive

# Toyota VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Toyota/Hilux/--  
VIN: AHTEW8CB201291596

Odometer Reading: 257241  
License Plate: KPC870MP

## Customer Information

Name: Dekra MFC AUCTION HOUSE







Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V11.40

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 5 )

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 1
SRS airbag	 0
Combination meter	 0
Cruise control	  0

## DTC ( 1 )

### ABS/VSC/TRC ( 1 DTC )

DTC	Description	Status
C1241	Low or high power supply voltage	Current

## Technician Notes

2016962809

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

