Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261026142015
Test Time: 2026-10-26 14:20:15
Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla/--
VIN: AHTLB52E103141531

Odometer Reading: 268172km
License Plate: JD37PLGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (3)

System	Status/DTC
Engine and ECT	0
Air conditioner	0
Immobilizer	0

DTC (0)

Technician Notes

2017317467

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.