



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250521161102
Test Time: 2025-05-21 16:11:02
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla/--
VIN: AHTLB52E303142213

Odometer Reading: 402907km
License Plate: KL86ZHGP

Customer Information

Name: Dekra MFC AUCTION HOUSE











Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.30

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(9)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 1
SRS airbag	 1
Main body	 0
Driver door motor	 0
Air conditioner	 0
Theft deterrent	 0
EMPS	 0
Radar cruise 1	  0

DTC (2)

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	Current

SRS airbag (1 DTC)

DTC	Description	Status
B1806	P squib circuit open	History

Technician Notes

2016886016



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.