



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250726120340
Test Time: 2025-07-26 12:03:40
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla/--
VIN: AHTLB52E403134881

Odometer Reading: 451833km
License Plate: HP66GXGP

Customer Information

Name: Dekra MFC AUCTION HOUSE










Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.30

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

| System | Status/DTC |
|-------------------|---|
| Engine and ECT |  0 |
| ABS/VSC/TRC |  2 |
| Main body |  0 |
| Driver door motor |  0 |
| Air conditioner |  0 |
| Cruise control |   0 |
| EMPS |  0 |
| Theft deterrent |  0 |

DTC (2)

ABS/VSC/TRC (2 DTCs)

| DTC | Description | Status |
|-------|----------------------------------|---------|
| C0278 | ABS solenoid relay circuit open | Current |
| C1241 | Low or high power supply voltage | Current |

Technician Notes

2016959360

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

