Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261021090026
Test Time: 2026-10-21 09:00:26
Technician: Barney

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P007119444

Odometer Reading: 523015km
License Plate: JX61GWGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (1)

System	Status/DTC
Engine	4

DTC (4)

Engine (4 DTCs)

DTC	Description	Status
P0400	Exhaust gas recirculation (EGR) flow	Pending
P0560	System voltage	Pending
P0400	Exhaust gas recirculation (EGR) flow	Current
P0560	System voltage	Current

Technician Notes

2017315065

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.