

Shop Name: --Tel: --Email: --Address: --

Report ID: MAXIA20250725114625 Test Time: 2025-07-25 11:46:25

Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/--Odometer Reading: 228121km VIN: AHTSS22P207140442 License Plate: KWD527NW

Customer Information

Name: MFC Dekra Nedbank Auction House Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01509

Version: V11.30 Repair Order Number: --

System Scanned(1)

Status/DTC System

Engine **Q** 1



Engine (1 DTC)

DTC	Description	Status
P0087	Fuel rail/system pressure too low	Current

Technician Notes

2016958195

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT

Page 1