Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261008154602
Test Time: 2026-10-08 15:46:02
Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P407152432

Odometer Reading: 311718km
License Plate: LJ40HSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (1)

System	Status/DTC
Engine	1

DTC (1)

Engine (1 DTC)

DTC	Description	Status
P0607	Control module performance	Current

Technician Notes

2017309124

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.