



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250822140030
Test Time: 2025-08-22 14:00:30
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P807113908

Odometer Reading: 170778km
License Plate: JR47GBGP

Customer Information

Name: Dekra MFC AUCTION HOUSE






Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.40

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 1
SRS airbag	 2
Combination meter	 1
Immobilizer	 0

DTC (4)

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	Current

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

Combination meter (1 DTC)

DTC	Description	Status
B1507	Turn signal circuit open	History

Technician Notes

2016988658



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.