



Shop Name: --  
Tel: --  
Email: --  
Address: --

Report ID: MAXIA20260804100325  
Test Time: 2026-08-04 10:03:25  
Technician: Werner

# Toyota VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Toyota/Hiace/Ventury/--  
VIN: AHTSS22P907106403

Odometer Reading: 450441km  
License Plate: JF76CPGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT  
Version: V11.70

Serial Number: VB8GJCC01509  
Repair Order Number: --



## System Scanned ( 1 )

| System | Status/DTC |
|--------|------------|
| Engine | 0          |



## DTC ( 0 )

## Technician Notes

2017279757

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.