



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260928152358
Test Time: 2026-09-28 15:23:58
Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P907146304

Odometer Reading: 178801km
License Plate: NONE plaste

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (1)

System	Status/DTC
Engine	0



DTC (0)

Technician Notes

2017304172

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

