



Shop: DEKRA MFC
 Tel: --
 Email: --
 Address: MFC Auction House
 Kempton Park

Report ID: MAXIA20240219114107
 Test Time: 2024-02-19 11:41:07
 Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
 VIN: AHTSX22P607107350

Odometer Reading: 200720km
 License Plate: JZ89KKGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE






Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V9.21

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 0
SRS airbag	 2
Combination meter	 0
Immobilizer	 0

DTC (2)

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

Technician Notes

2016272986

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.