Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261022155747
Test Time: 2026-10-22 15:57:47
Technician: Werner

Mazda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mazda/CX-5/--
VIN: JM6KF4W2AP0879999

Odometer Reading: 118885
License Plate: LG83FPGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (24)

System		Status/DTC
PCM(Powertrain control module)		2
TCM(Transmission control module)		0
ABS(Anti-lock brake system)		0
RCM(Restraint control module)		0
IC(Instrument cluster)		0
EPB(Electric parking brake)		0
EPS(Electronic-controlled power steering)		0
4X4M(4x4 control module)		0
AFS/ALM(Adaptive front lighting system/auto leveling module)	ADAS	0
AM(Amplifier module)		0
BSML(Blind spot monitoring (left))	ADAS	0
BSMR(Blind spot monitoring (right))	ADAS	0
CMU(Connectivity master unit)		1
DSM(Driver Seat Module (DSM))		0
EATC(Electronic air temperature controller)		0
FSC(Forward sensing camera)	ADAS	0
F_BCM(Front body control module)		0
HUD_MZ(Head up display)	ADAS	1
PLG_MZ(Power liftgate)		0
PSM_MZ(Parking sensor module)		0

R_BCM(Rear body control module)	0
SSU(Start stop unit)	1
VMC (View Monitor Camera)	0
WC_Qi_MZ(WC_Qi)	1

DTC (6)

PCM(Powertrain control module) (2 DTCs)

DTC	Description	Status
P2299:00-28	Brake Pedal Position/Accelerator Pedal Position Incompatible	CMDTCs
P252F:00-2F	Engine Oil Level Too High	CMDTCs

CMU(Connectivity master unit) (1 DTC)

DTC	Description	Status
B1238:16-0A	Speaker Amplifier	CMDTCs

HUD_MZ(Head up display) (1 DTC)

DTC	Description	Status
U3003:16-03	Battery Voltage	CMDTCs

SSU(Start stop unit) (1 DTC)

DTC	Description	Status
B13D3:16-08	PATS(Passive Anti Theft System) Transmitter	CMDTCs

WC_Qi_MZ(WC_Qi) (1 DTC)

DTC	Description	Status
U3003:16-08	Battery Voltage	CMDTCs

Technician Notes
2017315999

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.