

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/X-trail/--
VIN: JN1T33TD4Z0000507

Odometer Reading: 48772km
License Plate: LD30PGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned (19)

System		Status/DTC
ABS		 0
Air bag		 0
Meter/M&A		 0
Electric Power Steering (EPS)/DAST 3		 0
Left rear side radar		 0
Right rear side radar		 0
BCM		 4
Multi AV		 0
HVAC		 0
IPDM E/R		 0
Laser/radar		 1
Sonar		 1
Lane camera		 0
Shift		 0
AVM		 0
Chassis control		 0
Intelligent Cruise Control (ICC)/Advanced Driver Assistance System (ADAS) 2		 0
Hands-free module		 2
8 channel gateway 2		 0

 DTC (8)

BCM (4 DTCs)

DTC	Description	Status
C1711:7B	Left front tire pressure low	Past
C1712:7B	Right front tire pressure low	Past
C1713:7B	Right rear tire pressure low	Past
C1714:7B	Left rear tire pressure low	Past

Laser/radar (1 DTC)

DTC	Description	Status
C2582:97	Distance sensor	Past

Sonar (1 DTC)

DTC	Description	Status
B2729:97	Corner sensor [fl]	Past

Hands-free module (2 DTCs)

DTC	Description	Status
B2045:4A	Electric shift ID inconsistent	Past
B2088:44	One touch sensor (right front)	Past

Technician Notes
2017302494

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.