Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261029164326
Test Time: 2026-10-29 16:43:26
Technician: Werner

2010/09- Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

2010/09-/Nissan/X-trail/--
VIN: JN1TBAT31Z0710593

Odometer Reading: 264683km
License Plate: CBH607L

Customer Information

Name: MFC Dekra

Tel: 0104120214

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (7)

System	Status/DTC
Engine	2
ABS	0
Air bag	0
Meter/M&A	0
Electric Power Steering (EPS)/DAST 3	0
BCM	3
IPDM E/R	0

DTC (5)

Engine (2 DTCs)

DTC	Description	Status
P1111	Intake valve timing valve circuit (bank 1)	Current
P1614	Chain of IMMU-Key	1t

BCM (3 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	17 Time
B2190	Nissan anti-theft system (NATS) antenna AMP	Past
B2193	Chain of BCM-ECM	Past

Technician Notes

2017319447

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.