

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/X-trail/--
VIN: JN1TBNT32Z0017012

Odometer Reading: 59809km
License Plate: KS60NRGP

Customer Information

Name: --

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned (18)

System	Status/DTC
Engine	 0
Transmission	 0
ABS	 0
Air bag	 0
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 0
Air pressure monitor	 0
BCM	 0
HVAC	 0
Multi AV	 2
EHS/PKB	  2
IPDM E/R	 0
All mode AWD/4WD	 0
Adaptive light	  0
CAN gateway	 0
Auto back door	 4
Chassis control	  0
3-channel CAN gateway	 0

 DTC (8)

Multi AV (2 DTCs)

DTC	Description	Status
B1339:8F	Rear camera connection	Past
B1375:13	Rear camera power supply	Past

EHS/PKB (2 DTCs)

DTC	Description	Status
C1BDA	Left actuator fault (Command position unreachable)	Past
C1BDB	Right actuator fault (Command position unreachable)	Past

Auto back door (4 DTCs)

DTC	Description	Status
B2416	Right touch sensor circuit open	Past
B2417	Left touch sensor circuit open	Past
B2409	Half latch switch	Past
B2422	Back door status	Past

Technician Notes

2017296390

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.