

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla/--
VIN: JTDBP3AE90J181867

Odometer Reading: 126647km
License Plate: HDZ312L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (17)

System	Status/DTC
Engine and ECT	 1
Brake/EPB	 1
SRS airbag	 0
Combination meter	 0
Main body	 1
Master switch	 0
Driver door motor	 1
Right rear door motor	 1
Left rear door motor	 1
Passenger door motor	 1
Air conditioner	 0
Navigation system	 0
Starting control	 0
Radar cruise 1	  0
EMPS	 0
Steering angle sensor (SAS)	 0
Central gateway	 0

DTC (7)

Engine and ECT (1 DTC)

DTC	Description	Status
P1605	Rough idling	History

Brake/EPB (1 DTC)

DTC	Description	Status
C137BA2	Brake system control module "A" system voltage system voltage low	Confirmed

Main body (1 DTC)

DTC	Description	Status
U0155	Lost communication with instrument panel cluster (IPC) control module	History

Driver door motor (1 DTC)

DTC	Description	Status
B2312	Master switch of driver side door fault	History

Right rear door motor (1 DTC)

DTC	Description	Status
B2312	Power window switch of right rear door fault	History

Left rear door motor (1 DTC)

DTC	Description	Status
B2312	Power window switch of left rear door fault	History

Passenger door motor (1 DTC)

DTC	Description	Status
B2312	Power window switch of passenger door fault	History

Technician Notes

2017299282

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.