Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261023145448
Test Time: 2026-10-23 14:54:48
Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla Rumion/--
VIN: JTDDND22S00395083
Odometer Reading: 390362
License Plate: KWB373MP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (1)

System	Status/DTC
Engine	0

DTC (0)

Technician Notes

2017316659

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.