



Shop Name: --

Tel: --

Email: --

Address: --

Report ID: MAXIA20260928140815

Test Time: 2026-09-28 14:08:15

Technician: Werner

# Toyota VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Toyota/Corolla Rumion/--

VIN: JTDDND22S00A24130

Odometer Reading: 153228

License Plate: CV37FZGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT

Version: V11.80

Serial Number: VB8GJCC01509

Repair Order Number: --



## System Scanned ( 1 )

| System | Status/DTC |
|--------|------------|
| Engine | 0          |



## DTC ( 0 )

## Technician Notes

2017304211

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

