

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/H-1/iMAX/iLOAD/Grand starex(TQ)/--
 VIN: KMFWBX7KMJU974099

Odometer Reading: 228583
 License Plate: HH96JKGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V13.90

Serial Number: VB8GJCC01509
 Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	1
A/T (Transaxle)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0

DTC (1)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0532	A/C Refrigerant pressure sensor 'A' circuit input low	Active

Technician Notes

2017026797

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.