

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/H-100 Truck(HR)/--
VIN: KMFZBX7BLJU547075

Odometer Reading: 219160
License Plate: HP04LRGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(1)

System	Status/DTC
ENG (Engine)	0

DTC (0)

Technician Notes

2016370397

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.