Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261012152409
Test Time: 2026-10-12 15:24:09
Technician: Werner

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/H-100 Truck(HR)/--
VIN: KMFZBX7BLKU617550
Odometer Reading: 162904
License Plate: LR48XCGP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (1)

System	Status/DTC
ENG (Engine)	0

DTC (0)

Technician Notes

2017310511

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.