



Shop Name: --

Tel: --

Email: --

Address: --

Report ID: MAXIA20250902143054

Test Time: 2025-09-02 14:30:54

Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/H-100 Truck(HR)/--

VIN: KMFZBX7BLRU079468

Odometer Reading: 77064

License Plate: LR96NLGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V13.90

Serial Number: VB8GJCC01509

Repair Order Number: --



System Scanned (1)

System	Status/DTC
ENG (Engine)	0



DTC (0)

Technician Notes

2016999154

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

