



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260914115302
Test Time: 2026-09-14 11:53:02
Technician: Travino

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/H-100 Truck(HR)/--
VIN: KMFZBX7BLRU132595

Odometer Reading: 93976
License Plate: MC45BBGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (2)

System	Status/DTC
ENG (Engine)	 0
CODE (Transmitter Code Saving)	 0

DTC (0)

Technician Notes
2017298425

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

