

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Elantra/--

VIN: KMHD041BVJU752052

Odometer Reading: 101461

License Plate: HY01KLGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V13.50

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned(12)

System	Status/DTC
ENG (Engine)	0
A/T (Transaxle)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	0
CLU (Cluster Module)	0
TPMS (Tire Pressure Monitoring System)	0
CODE (Transmitter Code Saving)	0
A/C (Air Conditioner)	0
EPS (Motor Driven Power Steering)	0
BCM (Body Control)	0
SMK (Smart Key Unit)	0
SJB (Smart Junction Block)	0

DTC (0)

Technician Notes

2016317760

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.