



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250423090102
Test Time: 2025-04-23 09:01:02
Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Elantra(MD)/--
VIN: KMHDH41EMDU669971

Odometer Reading: 162473
License Plate: KK85YGGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.86

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(11)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 5
AB (Airbag)	 3
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
A/C (Air Conditioner)	 1
EPS (Motor Driven Power Steering)	 1
BCM (Body Control)	 0
SJB (Smart Junction Block)	 4

DTC (14)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (5 DTCs)

DTC	Description	Status
C1200	Left front vehicle speed sensor (VSS) circuit open or short	History
C1260	Steering angle sensor (SAS) circuit signal	Active
C1283	Yaw rate sensor (YRS) and 'G' sensor signal	History
C1623	CAN Timeout - Steering angle sensor (SAS)	History
C1687	CAN Timeout - Vehicle safety management (VSM) 2 (MDPS)	History



AB (Airbag) (3 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1346:00	Driver airbag (DAB) resistance too high (1st Stage)	Active
B1378:00	Front driver side airbag (DSAB) resistance too high	History

A/C (Air Conditioner) (1 DTC)

DTC	Description	Status
B1238	Ambient temperature sensor circuit open (high)	Active

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1259	Steering angle sensor (SAS) electrical fault	History

SJB (Smart Junction Block) (4 DTCs)

DTC	Description	Status
B2518	Left front turn signal lamp circuit open	History
B2519	Left rear turn signal lamp circuit open	History
B2520	Right front turn signal lamp circuit open	History
B2521	Right rear turn signal lamp circuit open	History

Technician Notes
2016851194

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.