Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261008173420
Test Time: 2026-10-08 17:34:20
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Tucson(TL)/--
VIN: KMHJ2813LJU658315

Odometer Reading: 131817
License Plate: FXZ390L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
ENG (Engine)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	0
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
BCM (Body Control)	0
SJB (Smart Junction Block)	0

DTC (0)

Technician Notes

2017309567

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.