

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/TUCSON(NX4)/--
VIN: KMHJB81DMPU184703

Odometer Reading: 98934KM
License Plate: NONE n

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (16)

System	Status/DTC
ENG (Engine)	✓ 0
A/T (Transaxle)	✓ 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	✓ 0
AB (Airbag)	✗ 2
CLU (Cluster Module)	✓ 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	✓ 0
A/C (Air Conditioner)	✓ 0
CODE (Transmitter Code Saving)	✓ 0
EPS (Motor Driven Power Steering)	✗ 1
AVN (Audio Video Navigation)	ADAS ✓ 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	✓ 0
WPC (Wireless Power Charger)	✓ 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	✓ 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	✓ 0
ICU (Integrated Central Control Unit)	✓ 0
RVM (Rear View Monitor)	ADAS ✓ 0



DTC (3)

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1684:00	Not-Configured device detected	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes

2017302457

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.