



Shop Name: Dekra MFC Auction House
 Tel: --
 Email: --
 Address: MFC AUCTION HOUSE
 M57 PRETORIA ROAD
 KEMPTON PARK

Report ID: MAXIA20250527115600
 Test Time: 2025-05-27 11:56:00
 Technician: Travino

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Kona (OS)/--
 VIN: KMHK281BTPU973170

Odometer Reading: 47848km
 License Plate: LL56XJGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V13.87

Serial Number: VB8GJCC01514
 Repair Order Number: --

System Scanned(15)

System	Status/DTC
ENG (Engine)	 0
CVT (Continuously Variable Transmission)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
A/C (Air Conditioner)	 0
EPS (Motor Driven Power Steering)	 0
AVN (Audio Video Navigation)	  0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
WPC (Wireless Power Charger)	 0
IGPM (Integrated Gateway Power Control Module)	 2
RVM (Rear View Monitor)	  0

DTC (2)

IGPM (Integrated Gateway Power Control Module) (2 DTCs)



DTC	Description	Status
B2352:00	Dedicated DRL (Left) circuit short to ground	History
B258B:00	Left front external tail lamp circuit short to ground	History

Technician Notes

2016891921

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.