



Shop: DEKRA MFC  
Tel: --  
Email: --  
Address: MFC Auction House  
Kempton Park

Report ID: MAXIA20231229100502  
Test Time: 2023-12-29 10:05:02  
Technician: Sbu

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/H-1/iMAX/iLOAD/Grand starex(TQ)/--  
VIN: KMHWH81KMJU953881

Odometer Reading: 188142  
License Plate: JXP681MP

## Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V13.40

Serial Number: VB8GJCC01482  
Repair Order Number: --

## System Scanned( 7 )

| System                                                 | Status/DTC                                                                              |
|--------------------------------------------------------|-----------------------------------------------------------------------------------------|
| ENG (Engine)                                           |  2   |
| A/T (Transaxle)                                        |  0   |
| ABS/ESP (Anti Lock Brake/Electronic Stability Program) |  0  |
| AB (Airbag)                                            |  1 |
| IMMO (Immobilizer)                                     |  0 |
| CODE (Transmitter Code Saving)                         |  0 |
| A/C (Air Conditioner)                                  |  0 |

## DTC ( 3 )

### ENG (Engine) ( 2 DTCs )

| DTC   | Description                                           | Status  |
|-------|-------------------------------------------------------|---------|
| P0532 | A/C Refrigerant pressure sensor 'A' circuit input low | Active  |
| P0685 | ECM/PCM Power relay control circuit/open              | Pending |

### AB (Airbag) ( 1 DTC )

| DTC      | Description         | Status  |
|----------|---------------------|---------|
| B1102:00 | Battery voltage low | History |

## Technician Notes

2016213909

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.