

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Picanto/Morning (JA)/--
VIN: KNAB2511LKT422895

Odometer Reading: 129727
License Plate: HWH664FS

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
A/C (Air Conditioner)	 0
EPS (Motor Driven Power Steering)	 0
IMMO (Immobilizer)	 0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B2500:00	Warning lamp failure	History

Technician Notes

2017297447

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.