

# Kia VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Kia/Picanto/Morning (JA)/--

VIN: KNAB2511LLT565258

Odometer Reading: 202210

License Plate: JH47BXGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT

Version: V14.10

Serial Number: VB8GJCC01509

Repair Order Number: --



## System Scanned ( 10 )

| System                                                   | Status/DTC |
|----------------------------------------------------------|------------|
| ENG (Engine)                                             | ✓ 0        |
| ABS/VDC (Anti Lock Brake system/Vehicle Dynamic Control) | ✓ 0        |
| AB (Airbag)                                              | ✗ 1        |
| CLU (Cluster Module)                                     | ✓ 0        |
| I-TPMS (I-Tire Pressure Monitoring System)               | ✓ 0        |
| A/C (Air Conditioner)                                    | ✓ 0        |
| EPS (Motor Driven Power Steering)                        | ✓ 0        |
| BCM (Body Control)                                       | ✓ 0        |
| CODE (Transmitter Code Saving)                           | ✓ 0        |
| IMMO (Immobilizer)                                       | ✓ 0        |



## DTC ( 1 )

### AB (Airbag) ( 1 DTC )

| DTC      | Description         | Status  |
|----------|---------------------|---------|
| B1102:00 | Battery voltage low | History |

## Technician Notes

2017304693

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.