Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261020110009
Test Time: 2026-10-20 11:00:09
Technician: Andrick

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Picanto/Morning (JA)/--
VIN: KNAB2511LLT595301

Odometer Reading: 158893
License Plate: KJJ616NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ENG (Engine)	0
ABS/VDC (Anti Lock Brake system/Vehicle Dynamic Control)	0
AB (Airbag)	0
CLU (Cluster Module)	0
I-TPMS (I-Tire Pressure Monitoring System)	0
A/C (Air Conditioner)	0
EPS (Motor Driven Power Steering)	0
IMMO (Immobilizer)	0

DTC (0)

Technician Notes

2017314594

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.