2023 Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

2023/Kia/Picanto/Morning (JA)/G 1.0 MPI KAPPA
VIN: KNAB2511LPT052387

Odometer Reading: 242710KM
License Plate: LB23PFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
ENG (Engine)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	1
CLU (Cluster Module)	0
I-TPMS (I-Tire Pressure Monitoring System)	0
A/C (Air Conditioner)	0
BCM (Body Control)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
RVM (Rear View Monitor) ADAS	0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

2017305262

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.