

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Picanto/Morning (JA)--
 VIN: KNAB2511MKT365271

Odometer Reading: 140432
 License Plate: JWH057MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
 Version: V14.10

Serial Number: VB8GJCC01509
 Repair Order Number: --

System Scanned (7)

System	Status/DTC
ENG (Engine)	1
A/T (Transaxle)	0
AB (Airbag)	0
CLU (Cluster Module)	0
A/C (Air Conditioner)	0
EPS (Motor Driven Power Steering)	0
IMMO (Immobilizer)	0

DTC (1)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0202:00	Cylinder 2 injector circuit/open	Active

Technician Notes

2017302491

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.