



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250416122113
Test Time: 2025-04-16 12:21:13
Technician: Werner

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Morning (TA)/--
VIN: KNABE511LGT136196

Odometer Reading: 157416
License Plate: DX25NDGP

Customer Information

Name: Dekra MFC AUCTION HOUSE







Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.86

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(6)

System	Status/DTC
ENG (Engine)	 0
AB (Airbag)	 1
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0
CODE (Transmitter Code Saving)	 0
IMMO (Immobilizer)	 0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

2016845858

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

