



Shop Name: --  
Tel: --  
Email: --  
Address: --

Report ID: MAXIA20250724162002  
Test Time: 2025-07-24 16:20:02  
Technician: Travino

# Kia VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Kia/Picanto/--  
VIN: KNABE511LHT427752

Odometer Reading: 249046  
License Plate: KN04MWGP

## Customer Information

Name: MFC Dekra Nedbank Auction House





Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V13.87

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned( 4 )

System	Status/DTC
ENG (Engine)	 0
AB (Airbag)	 1
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

## DTC ( 1 )

### AB (Airbag) ( 1 DTC )

DTC	Description	Status
B1102:00	Battery voltage low	History

## Technician Notes

2016957323

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.