



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250728121649
Test Time: 2025-07-28 12:16:49
Technician: Travino

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Rio(YB)/--
VIN: KNADB512LJ6123196

Odometer Reading: 148854km
License Plate: HH81ZPGP

Customer Information

Name: Dekra MFC AUCTION HOUSE











Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.87

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

| System | Status/DTC |
|--------------------------------------------------------|-----------------------------------------------------------------------------------------|
| ENG (Engine) |  0 |
| ABS/ESC (Anti Lock Brake/Electronic Stability Control) |  0 |
| AB (Airbag) |  0 |
| CLU (Cluster Module) |  0 |
| I-TPMS (I-Tire Pressure Monitoring System) |  0 |
| A/C (Air Conditioner) |  0 |
| BCM (Body Control) |  0 |
| IMMO (Immobilizer) |  0 |
| CODE (Transmitter Code Saving) |  0 |
| EPS (Motor Driven Power Steering) |  0 |

DTC (0)

Technician Notes

2016960379

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

